GOVERNMENT OF TELANGANA ABSTRACT

PUBLIC SERVANTS – PR&RD Department – Lapses in the maintenance of Office records and irregularities in execution of road work "Providing BT on R/f Pillikotiyal to Yeldurthy" in Medak District - Further action dropped – Orders – Issued.

· ·

PANCHAYAT RAJ & RURAL DEVELOPMENT (VIG.I) DEPARTMENT

<u>G.O.RT.No. 961</u> <u>Dated: 26-11-2016</u>

Read the following:-

- 1. From the CE, PR, Vigilance, Hyderabad, Lr.No.QC.4/ Vig./Med/ offinsp/2000, dt.02.08.2000
- 2. Govt.Memo No.28666/ Estt.I 1)/2000-6, dt.11.06.2004.
- 3. From the ENC, PR, Lr.No.Vig.II(4)/26171/2000, dt.12.12.2006
- 4. Govt.Memo No.1690/Estt.I/2007-1, dt.07.02.2007.
- 5. From the ENC, PR, Lr.No.Vig.I(6)/26171/2000, dt.11.07.2012.
- 6. From the ENC, PR, Lr.No.Vig.IV.(6)/26171/2000, dt. 28.03.2015 and 24.08.2016.

ORDER:

Certain lapses in the maintenance of Office of EE, PR, Medak and the Office of SE, PR, Medak were brought to the notice of the Government on the inspection of Chief Engineer, V&QC, PR, Hyderabad vide reference 1st read above. After examining the matter the Engineer-in-Chief, PR, Hyderabad was requested to initiate and finalize the disciplinary action against the officers responsible for execution of (5) substandard road works at his level vide reference 2nd read above.

- 2. In the reference 3rd read above, the Engineer-in-Chief, PR, Hyderabad has furnished draft article of charges against the officers responsible for the irregularities in the said works for initiating disciplinary action.
- 3. After examination of the matter, in the reference 4th read above, the Engineer-in-Chief, PR, Hyderabad was requested to call for the explanations of all the Engineering Personnel involved in the case in the first instance and examine their explanations and submit the same along with his specific remarks.
- 4. In the references 5th & 6th read above the ENC, PR, Hyderabad has reported that the SE, PR, Medak has submitted the report on the allegations in execution of Road from Pillikotyal to Yeldurthy, Medak District stating that on observation of the records and the explanations submitted by the Accused Officers, that the work was inspected by the EE, V&QC, Hyderabad after a lapse of (3) year defect liability period and the deficiencies are found well within the permissible limits prescribed by the Government and requested to drop further action against the Engineering Officials who involved in the above said road work.
- 5. Government, after careful examination of the matter, have decided and accordingly hereby drop further action against 1) Sri B. Suresh Kumar, the then Dy.EE, now I/c Chief Engineer, Panchayat Raj (Retd.), 2) Sri Sangameshwar, the then Dy.EE now Executive Engineer and 3) Sri Mohd. Saiduddin, the then Assistant Engineer on the lapses in the maintenance of Office records and irregularities in the execution of "Providing BT on R/f Pillikotiyal to Yeldurthy".
- 6. The Engineer-in-Chief, Panchayat Raj, Hyderabad shall take necessary action accordingly.

(BY ORDER AND IN THE NAME OF THE GOVERNOR OF TELANGANA)

S.P.SINGH SPECIAL CHIEF SECRETARY TO GOVERNMENT

To

The Individuals **through** the Engineer-in-Chief, Panchayat Raj, Telangana, Hyderabad.

The Engineer-in-Chief, Panchayat Raj, Hyderabad. Copy to:
The AG, Telangana State, Hyderabad.
SF/SC

//FORWARDED ::BY ORDER//

SECTION OFFICER